


TriplePlay™ Airflow Sensors - Disposable

10-10000-0010	TriplePlay™ Airflow Sensor, Disposable, Neonatal, 10 Pk
10-10000-0050	TriplePlay™ Airflow Sensor, Disposable, Neonatal, 50 Pk
10-10000-0210	TriplePlay™ Airflow Sensor, Disposable, Infant, 10 Pk
10-10000-0250	TriplePlay™ Airflow Sensor, Disposable, Infant, 50 Pk
10-10000-0310	TriplePlay™ Airflow Sensor, Disposable, Pediatric, 10 Pk
10-10000-0350	TriplePlay™ Airflow Sensor, Disposable, Pediatric, 50 Pk
10-10000-0410	TriplePlay™ Airflow Sensor, Disposable, Small, 10 Pk
10-10000-0450	TriplePlay™ Airflow Sensor, Disposable, Small, 50 Pk
10-10000-0510	TriplePlay™ Airflow Sensor, Disposable, Medium, 10 Pk
10-10000-0550	TriplePlay™ Airflow Sensor, Disposable, Medium, 50 Pk
10-10000-0610	TriplePlay™ Airflow Sensor, Disposable, Large, 10 Pk
10-10000-0650	TriplePlay™ Airflow Sensor, Disposable, Large, 50 Pk




TriplePlay™ Airflow Sensors - Reusable

10-14000-0201	TriplePlay™ Reusable Airflow Sensor - Infant
10-14000-0301	TriplePlay™ Reusable Airflow Sensor - Pediatric
10-14000-0401	TriplePlay™ Reusable Airflow Sensor - Small
10-14000-0501	TriplePlay™ Reusable Airflow Sensor - Medium



FM Airflow Sensor Interface Cables

	FM1 (Apnea, Hypopnea)
12-10170-0001	FM1 – NOMAD, Keyhole



PerfectFit 3D™ Effort Belt System


18-13208-0001	Perfect Fit™ 3D REUSABLE-Disposable Kit includes: 2- Perfect Fit™ 3-D sensors, 5-50 yard rolls of Effort Belt Strap, Keyhole -NOMAD
11-45008-0001	Perfect Fit™ 3D Effort Belt Sensor, Abdomen, Keyhole - NOMAD
11-45008-0002	Perfect Fit™ 3D Effort Belt Sensor, Chest, Keyhole - NOMAD
11-14001-5001	Perfect Fit™ 3D Button Hole Effort Belt Strap, 50 yard roll (20 studies)
11-14001-2501	Perfect Fit™ 3D Button Hole Effort Belt Strap, 250 yard (Five 50 yard rolls) (100 studies)

FastTrack™ Effort Pack

11-44000-7502	FastTrack Effort Pack, Adult
11-44000-7520	FastTrack Effort Pack, Adult, 20 Pack Box
11-44000-7540	FastTrack Effort Pack, Adult, 40 Pack Box

FastTrack™ Interface Cables and Interface Kit

18-01805-0001	FastTrack Effort Interface Kit, NOMAD
12-10171-0001	FastTrack Interface Cable, Chest NOMAD
12-10172-0001	FastTrack Interface Cable, Abdomen NOMAD



XM™ Extremity Movement Sensor

13-50000-0010	XM™ Extremity Movement Sensor, (10 pk)
13-50000-0050	XM™ Extremity Movement Sensor, (50 pk)
12-10173-0001	NOMAD, Interface Cable, LM1 or LM2

